

***FRAZIER PARK PUBLIC UTILITY
DISTRICT***

MANAGERS REPORT

For the month of August 2020

Prepared by:

Jonnie Allison, General Manager

Frazier Park Public Utility District

INFORMATIONAL ITEMS

I. WATER REPORT

Water Pumped this month 903,700 Cubic Ft.

Water sold: 1,253,690 Cubic Ft.

Water used for Fire & Flushing Line: ? Cubic Ft.

Lag Differential: -38.70%

Water Loss: ? Cubic Feet

Average chlorine residual: 1.04 MG/L

II. MAINTENANCE AND REPAIR: August 2020

Description	Current Month	Last Mo.	Calendar Yr to date
METER CHANGES	2	3	9
AFTER HOUR CALL OUTS	1	2	40
MAIN LINE LEAK REPAIRS	5	0	25
USA LOCATES	7	59	111
SERVICE/WORK ORDERS	173	218	1759
CUSTOMER "TURN-ONS"	0	4	15
CUSTOMER "TURN-OFFS"	2	1	14
LOCK OFF (NON PAYMENT)	0	0	17
SERVICE RECONNECT	0	0	19
SHUT OFF NOTICES	0	0	62
GALLONS CL2 USED	158	149	1188
WATER QUALITY COMPLAINTS	0	0	0

III. WATER QUALITY COMPLAINTS:

IV. ISSUES AND ACTIONS:

There was (5) mainline break(s) / repair(s) in the month of August 2020

Location	Dates	Comments
2832 Johnson	8/3/20	1" Clamps (1) ¾ Poly Push On and (1) ¾ Ranger Coupling
3916 Oregon	8/12/20	4" Steel Clamps (1) 4" Hymax, 4" x 2' PVC Pipe, 4"Cap
3916 Oregon	8/12/20	3" Steel Clamps (2) 3"Hymax Couplings & (1) 4" x 3' PVC Pipe
Buena Vista & Los Padres	8/13/20	2" Steel Clamps (1) 2.38 x 6, (2) 2.34- 6.69 x 7 1/2
4113 North End/Elm Trail	8/28/20	6" Steel Clamps (1) 6.56-6.96 x 7 1/2

- Nine (9) routine bacteriological samples were completed in compliance with the California Department of Public Health water quality regulations: Four (4) samples within the distribution system, and five (5) more at our wells and springs. Both Sam Young & Pine Canyon Springs are isolated from the system.
- There were (1) after hour callout(s) in the month of August 2020

Location	Dates	Comments
4113 North End	8/28/20	6" Steel- Augured into by SCE

V. NEW SERVICES INSTALLED: (0)

Address		Lot / Block / Tract	Size

VI. NEW BUSINESS:

- **APPLICATIONS FOR WATER SERVICE - 0**